




THE ROLE OF TPM FACILITATOR (บทบาท)

- TPM facilitator is in a **very important** function to help **workshops actively** implement small-group activity
(เป็นหน้าที่ที่สำคัญมากในการที่จะช่วยให้การปฏิบัติจริงลงถึงระดับกิจกรรมกลุ่มย่อยในสายการผลิต)
- TPM facilitator's role is to **grasp the overall flow of TPM** with...
 - 1) the right current direction at all
 - 2) the sufficiency fast of pace of progress(มีบทบาทในการกวาดตະล้อมส่วนต่างๆของ TPM ให้ไปในทางเดียวกันด้วยความถูกต้องและจังหวะความเร็วเหมาะสม)

Mapping Approach and Idea


TPM Strategy Map






Left ● ● ● ● ● Right
 0 1 2 3 4

- 0-15 Not efficient and very far from total productive
- 15-30 Low level of the efficient and far from total productive
- 30-45 Medium level of the efficient and mid-way to total productive
- 45-60 High level of the efficient and little far from total productive



Homogeneous profiles



Non-homogeneous profiles



	Big averaged size	Small averaged side
Homogeneous	A (Excellent)	B (Good)
Non- homogeneous	C (Fair)	D (Terrible)

HOMEWORKS

1. Introduce TPM
2. Set team
3. Select model machine/line/process/product
4. Form loss structure
5. Calculate OEE
6. Set target
7. Draft TPM policy → Strategy map → KPIs → Master plan
8. Training people
9. Kick-off

THE END

ธานี ถ่วมอ้อ

Tel: 081-918-9082

E-mail: thanee@tpmconsulting.org